

ADAMS SUBDIVISION (0174)

Mile Post	Rule 6.3	CP #'s	Radio Display: BJ South to Adams - 5252 -*81		Sta. #'s	Siding Feet
			WEST ▼ STATIONS ▲	EAST ▲		
314.0	YL ABS	N096	BJ SOUTH (3.6)	TY(M)	EC097	
310.4	TWC ABS		MARCY (23.6)	Y	EC101	8448
286.8			ROCK (10.4)		EC124	11094
276.4			CLYMAN JCT. (35.7)	T	EC135	12572
240.7			DALTON (19.1)		EC169	10602
221.6			OXFORD (19.7)		EC190	6044
201.9	YL ABS		ADAMS	Y	EC209	Yard
(112.1)						
SI-01 MAIN TRACK AUTHORITY						
ABS between CP N096 and Adams.						
TWC/ABS between MP 308.4 and MP 204.0.						
Yard Limits between MP 314.0 and MP 308.4; MP 204.0 and Adams.						
SI-02 MAXIMUM SPEED TABLE						
Maximum Speed			MPH			
Between Mileposts						
314.0 and 201.9						
(Except as Below)..... 50						
314.0 and 258.0..... 30						
245.5 and 244.5..... 40						
232.5 and 229.7..... 40						
228.0 and 201.9..... 30						
SI-03 OTHER SPEED RESTRICTIONS						
Maximum Speed			MPH			
1. Thru Sidings & Turnouts						
All Sidings..... 10						
2. Dual Control Switch Turnouts						
CP N096..... 10						
Except Milwaukee Subdivision Track 1 to Adams Subdivision..... 30						
3. Misc. Speed Restrictions (No Exceptions.)						
SI-04 MAIN TRACK DESIGNATIONS - None.						
SI-05 MILEPOST EQUATIONS - None.						
SI-06 DTC BLOCK LIMITS - None.						
SI-07 ITEM 13 TRAIN DEFECT DETECTORS						
(#) 298.4						
(#) 236.2						
SI-08 RULES ITEMS - None.						
SI-09 FRA EXCEPTED TRACKS - None.						

SI-10 BUSINESS TRACKS		
Track Name	MP	STA. #'S
Bark Pit E.....	302.3	EC109
North Lake W.....	297.8	EC113
Mapleton W.....	292.5	EC118
Lebanon W.....	282.5	EC128
South Beaver Dam	264.4	EC147
South Randolph W.....	256.8	EC154
Friesland E.....	250.6	EC161
Glenoak W.....	231.0	EC179
Grand Marsh	210.2	EC201
SI-11 INDUSTRIAL LEADS - None.		
SI-12 TONNAGE RESTRICTIONS/TPOB		
Maximum Gross Weight: 143 Tons		
SI-13 TRAIN MAKE-UP RESTRICTIONS - None.		
SI-14 MISC. INSTRUCTIONS		
Clyman Jct.: Normal position for north wye switch is for Old Lakeshore main track.		
Adams: Loaded Bulk Commodity Unit Trains are restricted from using the crossovers from the main track to the yard at the east end and tracks 5 through 9 and track 12.		
Item 2-C: Exception 2 applies between MP 228.5 and Adams.		