

BMI SUBDIVISION (0762)

Mile Post	Rule 6.3	CP #'s	Radio Display: Boulder Jct. to Henderson-- 2727(*12) -		Sta. #'s	Siding Feet
			WEST ▼ STATIONS	EAST ▲		
0.0	TWC		BOULDER JCT. (9.9)		CX486	
9.9	TWC YL		HENDERSON (1.0)	Y	CN810	
10.9			END OF TRACK	Y		
(10.9)						
SI-01 MAIN TRACK AUTHORITY						
TWC Between MP 0.0 and MP 10.9.						
Yard Limits Between MP 8.5 and MP 10.9.						
SI-02 MAXIMUM SPEED TABLE						
Maximum Speed			MPH			
Between Mileposts 0.0 and 10.9 (Except as Below) 10						
SI-03 OTHER SPEED RESTRICTIONS						
Maximum Speed			MPH			
1. Thru Sidings & Turnouts (No Exceptions.)						
2. Dual Control Switch Turnouts (No Exceptions.)						
3. Misc. Speed Restrictions Henderson - BMI Lead and Yard Tracks... 5						
SI-04 MAIN TRACK DESIGNATIONS - None.						
SI-05 MILEPOST EQUATIONS - None.						
SI-06 DTC BLOCK LIMITS - None.						
SI-07 ITEM 13 TRAIN DEFECT DETECTORS - None.						
SI-08 RULES ITEMS						
Rule 5.4.4 in effect						
SI-09 FRA EXCEPTED TRACKS - None.						
SI-10 BUSINESS TRACKS - None.						
SI-11 INDUSTRIAL LEADS - None.						
SI-12 TONNAGE RESTRICTIONS - None.						
SI-13 TRAIN MAKE-UP RESTRICTIONS - None.						
SI-14 MISC. INSTRUCTIONS						
Pioneer Yard: Derail on lead into Pioneer Yard.						

