

CONDON SUBDIVISION (0834)

Mile Post	Rule 6.3	CP #'s	Radio Display: Gilliam to Arlington-2727(*06) . -		Sta. #'s	Siding Feet
			SOUTH ▼ STATIONS	NORTH ▲		
0.0	TWC		ARLINGTON (7.3)		OX638	
7.3			SHUTLER (3.2)		ON308	
11.5			GILLIAM		ON311	
(11.5)						
SI-01 MAIN TRACK AUTHORITY						
TWC in effect Entire Subdivision.						
SI-02 MAXIMUM SPEED TABLE						
Maximum Speed			MPH			
Between Mileposts 0.00 and 11.5						
(Except as Below)					25	
0.0 and 0.4.....					15	
SI-03 OTHER SPEED RESTRICTIONS						
Maximum Speed			MPH			
1. Thru Sidings & Turnouts (No Exceptions.)						
2. Dual Control Switch Turnouts (No Exceptions.)						
3. Misc. Speed Restrictions (No Exceptions.)						
SI-04 MAIN TRACK DESIGNATIONS - None.						
SI-05 MILEPOST EQUATIONS - None.						
SI-06 DTC BLOCK LIMITS - None.						
SI-07 ITEM 13 TRAIN DEFECT DETECTORS - None.						
SI-08 RULES ITEMS						
Rule 5.4.4 in effect.						
SI-09 FRA EXCEPTED TRACKS - None.						
SI-10 BUSINESS TRACKS - None.						
SI-11 INDUSTRIAL LEADS - None.						
SI-12 TONNAGE RESTRICTIONS - None.						
SI-13 TRAIN MAKE-UP RESTRICTIONS - None.						
SI-14 MISCELLANEOUS INSTRUCTIONS - None.						

