

HARTLAND SUBDIVISION (185)

Mile Post	Rule 6.3	CP #’s	Radio Display: Hartland to Curtis -5252		Sta. #’s	Siding Feet
			SOUTH ▼ STATIONS	NORTH ▲		
106.3	TWC		HARTLAND (0.7)		DH014	
107.0			DME CONN (12.0)			
119.0	YL		ALBERTA LEA (0.4)	Y (X)IMRL(S)	DM099	
119.4		U251	CURTIS	Y	DM100	

(13.1)

SI-01 MAIN TRACK AUTHORITY

TWC Between MP 106.3 and MP 117.0.

Yard Limits Between MP 117.0 and Curtis.

SI-02 MAXIMUM SPEED TABLE

Maximum Speed	MPH
Between Mile Posts 106.3 and 119.4	
(Except as Below).....	30
115.5 and 119.4	10

SI-03 OTHER SPEED RESTRICTIONS

Maximum Speed	MPH
1. Thru Sidings & Turnouts (No Exceptions.)	
2. Dual Control Switch Turnouts (No Exceptions.)	
3. Misc. Speed Restrictions (No Exceptions.)	

SI-04 MAIN TRACK DESIGNATIONS - None.

SI-05 MILE POST EQUATIONS - None.

SI-06 DTC BLOCK LIMITS - None.

SI-07 ITEM 13 TRAIN DEFECT DETECTORS - None.

SI-08 RULES ITEMS - None.

SI-09 FRA EXCEPTED TRACKS - None.

SI-10 BUSINESS TRACKS - None.

SI-11 INDUSTRIAL LEADS - None.

SI-12 TONNAGE RESTRICTIONS - None.

SI-13 TRAIN MAKE-UP RESTRICTIONS - None.

SI-14 MISC. INSTRUCTIONS

Item 2-C: Exception 2 applies.

