

NASHVILLE SUBDIVISION (0411)

Mile Post	Rule 6.3	CP #'s	Radio Display: Perkins to Hope -2727		Sta. #'s	Siding Feet
			SOUTH ▼ STATIONS	NORTH ▲		
493.1	TWC		PERKINS (9.9)	BY	XJ036	
483.1			NASHVILLE (25.3)	Y (X)KCS(S)	XJ026	
457.5	YL		HOPE	BY	X 458	
(35.3)						
SI-01 MAIN TRACK AUTHORITY						
TWC in effect Entire subdivision.						
Yard Limits Between MP 493.1 and MP 492.0; MP 484.0 and MP 481.2; MP 465.0 and MP 457.5.						
SI-02 MAXIMUM SPEED TABLE						
Maximum Speed			MPH			
Between Mileposts						
493.1 and 457.5						
(Except as Below) 25						
483.6 and 482.3 10						
462.8 and 457.5 10						
SI-03 OTHER SPEED RESTRICTIONS						
Maximum Speed			MPH			
1. Thru Sidings & Turnouts (No Exceptions.)						
2. Dual Control Switch Turnouts (No Exceptions.)						
3. Misc. Speed Restrictions (No Exceptions.)						
SI-04 MAIN TRACK DESIGNATIONS - None.						
SI-05 MILEPOST EQUATIONS - None.						
SI-06 DTC BLOCK LIMITS - None.						
SI-07 ITEM 13 TRAIN DEFECT DETECTORS - None.						
SI-08 RULES ITEMS						
Rule 5.4.4 is in effect on this subdivision.						
Rule 8.3: No normal position for siding switch on north Hope siding (Little Rock Sub.) at MP 457.5.						
SI-09 FRA EXCEPTED TRACKS - None.						
SI-10 BUSINESS TRACKS						
Track Name		MP	STA. #'S			
Cent Lumber		460.8	. . .			
North Hope		461.0	XJ004			
Hope Industry Track		462.2	. . .			
Ozan Creek		472.0	XJ013			
SI-11 INDUSTRIAL LEADS - None.						
SI-12 TONNAGE RESTRICTIONS - None.						
SI-13 TRAIN MAKE-UP RESTRICTIONS - None.						
SI-14 MISC. INSTRUCTIONS - None.						

