

ROCKPORT SUBDIVISION (0644)

Mile Post	Rule 6.3	CP #'s	Radio Display: Tower 112 to Coal Plant Jct. -4242		Sta. #'s	Siding Feet
			SOUTH ▼ STATIONS	NORTH ▲		
0.0	TWC	SA211	TOWER 112 (11.0)	(X)UP(M)	SO220	
11.0			COAL PLANT JCT.		AZ015	
(11.0)						
SI-01 MAIN TRACK AUTHORITY						
TWC Between MP 0.0 and MP 11.0.						
SI-02 MAXIMUM SPEED TABLE						
Maximum Speed			MPH			
Between Mileposts 0.0 and 11.0						
(Except as Below)					25	
0.2 and 1.0					10	
SI-03 OTHER SPEED RESTRICTIONS						
Maximum Speed			MPH			
1. Thru Sidings & Turnouts (No Exceptions.)						
2. Dual Control Switch Turnouts (No Exceptions.)						
3. Misc. Speed Restrictions (No Exceptions.)						
SI-04 MAIN TRACK DESIGNATIONS - None.						
SI-05 MILEPOST EQUATIONS - None.						
SI-06 DTC BLOCK LIMITS - None.						
SI-07 ITEM 13 TRAIN DEFECT DETECTORS - None.						
SI-08 RULES ITEMS - None.						
SI-09 FRA EXCEPTED TRACKS - None.						
SI-10 BUSINESS TRACKS - None.						
SI-11 INDUSTRIAL LEADS						
Rockport Industrial Lead: MP 11.0 to MP 16.0 (end of track). Wye switch at MP 12.6 leading to CPS plant may be left lined as last used. Maximum gross weight-143 tons.						
SI-12 TONNAGE RESTRICTIONS/TPOB						
Maximum gross weight: 143 tons.						
SI-13 TRAIN MAKE-UP RESTRICTIONS - None.						
SI-14 MISC. INSTRUCTIONS						
Northward trains to avoid blocking public crossings, verify movement is authorized past Tower 112 before proceeding beyond MP 11.0.						

